

Calori House

3021 E Chevy Chase Dr
Glendale Historic Register #23

October 2021





















Proposed Mills Act Conditions



Repair crack in stucco at
northeast corner of house



Repair and repaint window and lintel - south exterior



Repari windows - west exterior



Replace window in shower

Close gaps
around garage
door

Extend gutter
downspout

