



1 Honolulu Avenue north of Canada Valley Regional Park looking south.



2 Verdugo Wash at New York Avenue looking north.



3 Verdugo Wash at New York Avenue looking south.



4 Verdugo Wash at Whiting Woods Road looking north.



5 Verdugo Wash at Whiting Woods Road looking south.



6 Verdugo Wash at Shirleyjean Street looking north.



7 Verdugo Wash at Glenoaks Boulevard and Louise Street looking west.




8 Verdugo Wash at Glenoaks Boulevard and entrance to Nestle USA looking west.



9 Verdugo Wash at Glenoaks Boulevard and Central Avenue looking west.

VERDUGO WASH EXISTING CONDITIONS

2 August 2016



VERDUGO WASH EXISTING CONDITIONS

2 August 2016